Industrial Engineer

Devoted to the Maintenance and Operation of
Electrical and Associated Mechanical
Systems in Mills and Factories

Volume 83

January to December, 1925

McGRAW-HILL COMPANY, INC.
7 South Dearborn Street
CHICAGO, ILLINOIS

UNIV. OF MINN. LIBRARY

INDUSTRIAL ENGINEER

INDEX TO VOLUME 83

January to December, 1925

GENERAL INDEX

Pages by Months

January	1 to 48
February	49 to 116
March	117 to 164
April	165 to 212
May	213 to 260
June	261 to 308
July	309 to 356
August	357 to 404
September	405 to 460
October	461 to 508
November	509 to 556
December	557 to 604

A

Accident prevention (see Safety).
Air compressor, using vacuum pump as (R. A. Kiefer), (E. H. Laabs), 245, (C. O. Sandstrom), 343.
Alarms (see Signals):
Allis-Chalmers Manufacturing Company's plants, *2.
Alternators coupled to same shaft, paralleling (R. S. Huntington), *153, comment (Edward D. Carter), 250.
Ammeters (see under Meters).
Arc welding (see Welding).
Armatures (see under Motor Reconnection and Repair).
Association of Iron & Steel Electrical Engineers:
——Convention, program, *438.
——Convention, report of, *462.
Babbitt, precautions necessary in the use of (Maurice C. Cockshott), 42.
Batteries, storage:
——Charging, pointers on (G. H. McKelway), 548.
——Repairing (F. J. H. Krause), 256.
Bearings:
——Ball:
Cost, do they justify their (Howard Maxwell), *12.
Lineshafts on, operating heavy-duty (Stanley D. Berg), 103.
Lubrication of, hanger boxes, 351.
Shafts keen under inner rings of, why, 253, comment (R. L. Brown), 300.
——Changes that have taken place in (L. A. Hillman), *127.
——Drip pan prevents oil dripping, oversized, *551.
——Dust seal for hanger box and pillow blocks, *254.
——Frozen motor, removed and repaired (Donald A. Hampson), *253.
——Motor, proper care of (George B. Heron), *299.
——Motor, selecting material for small (Carl G. Howard), 599.
——Pump:
Centrifugal, renewals in (Maurice Cockshott), 398.
Tight, motor trouble traced to (Grady H. Emerson), 156.
—— Roller:
Cost, do they justify their (Howard Maxwell), *12.
Improved, *601.
Repairing, in loose pulleys (Donald A. Hampson), 597.
——Running in, which heat up when new, helps on (M. J. E.), 352.
——Sleeve, use of an improved type of (J. S. Murray), *473.
——Steel pipe in place of cast shell, cost decreased by using (D. W. Blakeslee), 156.
——Trends and new practices in use of (G. A. Van Brunt), *55.

B

Belts:
——Capacity, how service conditions affect (R. F. Jones), *265.
——Discarded, for small machine drives, working up, 451.
——Double, reused on small drives, old, 500.
——Drivings, on short centers with high pulley ratios, *43.
——Installation, saving half on a (editorial comment), 90.
——Long, drive, handling (Donald A. Hampson), *201.
——Quality of leather, determining the (Louis W. Arny), *479.
——Reclaiming leather (J. Edgar Rhoads), 190.
——Short-center, drives using idlers, laying out (Robert W. Drake), *166.
——Slip as safety link in machine drives (E. D. F.), *103.
——Trends and new practices in use of (G. A. Van Brunt), *55.
——Trouble to happen, why wait for (editorial comment), 338.
Bolts, dimension specification for ordering stud (Arthur L. Greene), *353.
Books, practical:
——Batteries, storage (George Wood Vinal), 162.
——Calculus for home study, practical (Claude Irwin Palmer), 162.
——Drafting and design, electrical (Calvin C. Bishop), 210.
——Electrical engineers' handbook for (edited by Harold Pender), 114.
——Electricity for practical men, applied (Arthur J. Rowland), 114.
——Electroplating and electroforming, principles of (William Blum), 114.
——Engineering, elements of electrical (George D. Shepardson), 162.
——Engineering in American industry (Conrad Newton Lauer), 210.
——Eye hazards in industrial occupations (Louis Resnick and Lewis H. Carris), 210.
——Gas, natural (Lester Clyde Lichty), 162.
——Heating and ventilating engineers' guide, American Society of, 210.
——Industrial electricity (Chester L. Dawes), 210.
——Industrial electricity—direct current machines (William H. Trimble), 114.
——Life work, choosing your (William Rosengarten), 162.
——Light and work (M. Luckiesh), 114.
——Magnets (Charles R. Underhill), 114.
——Mathematical analysis, practical (H. Von Sanden), 210.
——Radio, practical (James A. Mover and John F. Wostrel), 210.
——Substation operation (Edwin Kurtz), 210.
——Tulley's handbook in three volumes (James F. Hobart, revisor), 162.
——Welding and cutting manual, arc, 162.
——Wiring, conduit (Terrell Croft), 114.
——Wiring, electric (Albert A. Schuhler), 162.
Braymer, O. H. (Practical Pete), *262.
Brushes:
——Selecting, points to consider in, 499.
——Maintenance, commutator and (E. S. Howe), *575.
Buick Motor Company's factory, housekeeping in the (Practical Pete), *405.
Buildings (see Plants).
Busbar, device for bending copper (S. H. Samuels), *547.
Business Publishers' International Corporation formed, 460.

C

Cables:
——Size of, for intermittent rated motors, determining (Phil D. Comer), (G. H. McKelway), 195, and (George Cropper), (Donald Ferguson), (R. F. Emerson), 291.
——Splice on heavy, making a sleeve (S. H. Samuels), *152, and (G. H. McKelway), 596.
Car to carry men to top of incline, electric, *397.
Ceiling as safeguard when cutting holes, shoring up, *445.
Chain drive:
——Enclosing and lubricating silent (Paul Wheeler), *133.
——Feed-belt drive improved operation, simple changes in a (Donald A. Hampson), *551.
——Individual motors and (Dean W. Taylor), *214.
——Parallelism of shafts on a, checking (Donald A. Hampson), *501.
——Problem (Practical Pete), *557.
——Sprockets for, living up (E. H. Laags), 195, (P. S. Pender), *32.
Charts (see Records):
Circuit breakers, oil:
——Electric Power Club's instructions for installing, *373.
——Oil for, inspection and testing of, 153.
——Selection and maintenance (George A. Burnham), 465, (M. J. Wohlgemuth and E. K. Read), 468.
Clutches, trends and new practices in use of (G. A. Van Brunt), *55.
Coal (see Handling materials).
Code, National Electrical.
——Changes in, summary of (G. A. Van Brunt), 529, (editorial comment), 537.
——Give the, a chance to answer your questions (editorial comment), 189.
Coils (see under Motor Reconnection and Repair).
Communication (see Signals and Telephones).
Commutators (see Motor Repairs).
Compensator (see Motor control).
Concrete:
——Conduit, cleats or bolts to, attaching (S. W. Stearns), 198.
——Pillars, supporting lineshafting on (E. I. Pease), (H. D. Fisher), (H. S. Rich), (E. L. Way), (E. H. Laabs), (C. O. Sandstrom), *240.
Condenser, using rotary converter as synchronous (Robert W. Drake), *262.
Conductors (see Cables and Wires).
Conduit (see also Wiring):
——Ceiling beams, lining up, on (P. S. Pender), 93.
Conduit (Continued):
——Fittings, threadless, *601.
Construction during 1925, new industrial (editorial comment), 90.
Control, motor (see Motor control).
Converter as synchronous condenser, using rotary (Robert W. Drake), *262.
Costs:
——Pays the fiddler, when you dance some one (Practical Pete), *357.
——Price, do not judge by the (editorial comment), 385.
——Savings depend on vision as well as volume, plant (editorial comment), 384.
Couplings:
——Flexible, improved, *602.
——Flexible, will they reduce gear shock on motors? (William J. Mildon), 538.
——Trends and new practices in use of (G. A. Van Brunt), *55.
Covers for idle machines are a good investment (editorial comment), 437.
Cranes (see also Hoists):
——A.c., trouble on, corrected by dynamic braking (R. F. Emerson), *448.
——Monorail, trolley wire supports for (M. H. Case), (Lachlan A. McEwan), (Earle N. Dillard), (A. Fiess), *386.
——Motors in parallel on bridge motion of, operating (D. W. Blakeslee), (A. J. Conway), 340, (R. F. Emerson), 498.
——Operators of overhead wires, warning (R. H. Bahney), *447.
——Stopping, at point of small clearance, safety device for (J. Elmer Housley), *99.
——Trolley wire when it breaks, safety device for killing live (O. E. Bricker), *101.
——Yard, overcomes bad loading condition (Donald A. Hampson), *296.
Crusher, motor-driven pot (H. S. Rich), *155.
Cutting outfits, odd-time uses of, *495.
Cutting plate, construction of foot-operated broach for (G. A. Luers), *502.

D

Demand limitator, power, *602.
Diagram (see Records).
Distribution:
——Grounding secondary of 3-phase, 220-440-volt (Edward A. Gibbs), (H. S. Rich), (Donald Ferguson), (C. Otto von Dannenberg), 148.
——Grounds, using graphic meters for detecting (R. H. Bahney), *415, (editorial comment), 436.
——Overhead electrical circuits, layout of (J. Elmer Housley), *358.
——Woodworking plant, power service layout for a (Francis A. Westbrook), *316.
Drills, heavy-duty, ½-in., 600.
Dust:
——Removing, produced in industrial plants (Charles L. Hubbard), *320.
——Separating, from air in industrial plants (Charles L. Hubbard), *366.

E

Eaves troughs, two ways to get longer life from (S. W. Stearns), 150.
Editorial comments, 30, 90, 140, 188, 238, 286, 338, 384, 436, 488, 536, 584.
Electric Power Club:
——Circuit breakers and power switching equipment instructions for installing oil, *373.
——Motors, how variations in voltage and frequency affect induction, 396.
——Switchboards, recommendations on installation and care of power, *327.
Electromagnets (see Magnets).
Elevators, electric:
——Man, past top floor, stop which prevents riding, *197.
——Motor, trouble caused by plugging (H. S. Rich), (W. J. Neustedter), 96.
EMF Electrical Year Book sold to McGraw-Hill Company, 604.
Engineer, safety and the electrical (John A. Oartel), 471.
Equipment, make conditions justify the use of special (editorial comment), 338.
Executives come from, where will your (editorial comment), 30.
Factor, power (see Power factor).

F

Fans (see also Motors and Motor reconnection and repair).
——Lineshaft driven, helps keep the shop cool, *393.
Fiddler, when you dance some one pays the (Practical Pete), *357.
Filing (see Records).
Fires:
——Could you afford to have a, in your plant? (Editorial comment), 488.
——Organization of fire prevention in industrial works (K. P. Babcock), *98.
——Poor housekeeping causes most plant (editorial comment), 239.
——Prevention in industrial plants, rules governing (G. A. Luers), 247.

*Indicates illustrated articles

OCT 1 1927

Floors:
——Gratings for openings, metal (Donald A. Hampson), *546.
——Linoleum, making a close seam when laying, 296.
——Saw to cut out wooden, *247.
——Sweepings, trap for, *197.
——Trucking runways, comparative costs on three types of, for (L. J. Clayton), 249.
Fumes, gases and vapors, removing obnoxious (Charles L. Hubbard), *276.
Furnace, electric melting (J. A. Seede), 470.
Fuses:
——Accessibility of, is big factor in laying out power circuits (Edwin V. Lambert), *154.
——Capacities by different colors, designatings (A. W. Oppmann), 40.
——Color scheme prevents misuse of (Charles R. Hepner), *228, editorial comment, 238.
——440-volt circuits, voltage rating for (H. T. Bussmann), (Edward James), (J. L. Broyles), (P. S. Pender), (Phil. D. Comer), (Earl Baber), 96, (Grady H. Emerson), (L. T. Johnson), (G. H. McKelway), 245.
——Open, failure of best lamps to show (Dean W. Taylor), 99.
——Renewable link, tool for inserting (W. L. Stevens), *198.
——Renewals on the night shift (E. B. F.), 41.
——Replaceable, simple and easily (Harold F. Benson), *600.
——30 amp. and 60 amp., use of (E. T. Carpenter), 448.
——Wire, current values required to fuse solid copper (Frederick Krug), 449.

G

Gases, fumes and vapors, removing obnoxious (Charles L. Hubbard), *276.
Gears:
——Aligning motor pinion with the gear it drives (Donald A. Hampson), *398.
——Bevel, reducing cost when ordering (Warren G. Jones), 254.
——Breakage of, stopping (Grady H. Emerson), (C. O. Sandstrom), 491.
——Reductions with oil circulating system, modernizing sets of old-type (Maurice C. Cockshott), *550.
——Shock on motors, will flexible couplings reduce? (William J. Mildon), 538.
General Electric Company's plants, *2.
Generators:
——A. C., used as synchronous motor (Lee F. Dann), 195, (G. B. Heron), 292.
——Automobile, trouble with rewound (Edward James), George D. Ringness), 245, (B. Belcher), 343.
——Excitation for, emergency (C. Otto von Dannenberg), 386.
——43 years ago, installed (Practical Pete), *509.
——Motor as, operating d.c. (Nicholas J. Weiss), (W. Montelius Price), (J. M. Walsh), (C. Otto von Dannenberg), 494.
——One, with two engines, driving (Grady H. Emerson), 243.
——110-volt, for 6 volts, rewinding (William B. Cone), 340.
——30 years of service (Practical Pete), *165.
——Turbo (see Turbo-Generators).
Glass, drilling holes through plate, (D. W. Blakeslee), (John Griva), (A. C. Barker), 592.
Greases for industrial lubrication, using oils and (Frank E. Gooding), *558.
Growler, construction and uses of a (W. E. Paulsen), *502.

H

Handling materials (see also Conveyors, Cranes, Hoists, Magnets, Tractors, Trailers, Trucks, etc.).
——Air in industry, by, (Charles L. Hubbard), *427.
——"Cat's paw" hitch for lifting heavy loads (S. H. Samuels), *393.
——Coal, equipment, interlocking the control of (Roger F. Emerson), *251.
——Devices pay for themselves, where (Frank E. Gooding), *65.
——Following precedent or following the leader (editorial comment), 31.
——Sling chains are abused, ways in which (David Fliegelman), *223.
——Ton of output, how many tons do you handle per (editorial comment), 339.
——Tripod from conduit, making (W. B. Cone), *249.
Heaters, electric (see Heating).
Heating, electric:
——A. I. & S. E. E., committee report (George H. Schaeffer), 469.
——Cooperage plant, in (S. A. Frost), *547.
——Developments in (Arthur J. Whitcomb), *107.
——Hard-to-heat spots in your plant, have you any (editorial comment), 537.
——Heat treating applications, electric (E. A. Hurme), 469.
——Ingots, of (Ralph A. Butler), 471.
——Locomotive wheel tires, to remove (J. H. Gallant), *44.
——Space in battery manufacture (P. E. Norris), *251.
——Wood before bluing, electric heat supplants steam for preheating (J. L. Faden), *199.
Hiring and firing of men, the (editorial comment), 489.
Hoists:
——Air, saves floor space in steel chip disposal (W. H. Wineman), *347.
Hoists (Continued):
——Controller, new 602.
——Efficiency of elements, of hoisting mechanisms, determining combined (William L. Laing), 102.
——Sling chains are abused, ways in which (David Fliegelman), *223.

I

Ice machine shaft turned without removing (Donald A. Hampson), 205.
Incandescent lamp (see Lamps).
Industrial centers, growth of well-known (Frank E. Gooding), *6.
"Industrial Engineer's" new boss (Practical Pete), *262.
Inspection and Maintenance:
——Inspection:
Bearings, proper care of motor (George B. Heron), *299.
Charting frequency of making, 97.
Motor, form helps in training inspectors (C. H. Hart), *39.
——Maintenance:
Brush and commutator (E. S. Howe), *575.
Corona Typewriter Company, in (C. D. Corwin), *50.
Cost, the wrong way to decrease (editorial comment), 238.
Covers for idle machines (editorial comment), 437.
Diaries on jobs, advantages of keeping (L. J. Clayton), 346.
Difficulties instead of overcoming them, avoid (editorial comment), 287.
Grounding circuits, *39.
Repairs that show the value of experience, reminiscences on mechanical (Donald A. Hampson), 203.
Small-plant, problems (Maurice C. Cockshott), *567.
Spare equipment also, test and maintain (editorial comment), 437.
Spare part stocks as breakdown insurance (editorial comment), 188.
Steel mills of large motors in (O. Needham), *423.
Today will save repairs tomorrow (editorial comment), 385.
Tools, developments in, *84.
Tools for, portable power-driven (editorial comment), 489.
——Trouble shooter for a machinery builder, reminiscences of a (Practical Pete), *131, *182.
Installation (see Motor installation).
Instruments (see also Meters).
——Overhauling electrical measuring (J. D. Zook), *219.
Insulation:
——Motor, using megger for testing (E. I. Pease), (William Glameyer), (C. Otto von Dannenberg), (A. C. Roe), 442, (Lee F. Dann), (Edward James), (H. Charlton), (Ralph McKinney), 344.
——Motor, voltage for testing, 206.
——Slot, thickness of mica required for (Edward James), (A. C. Roe), (Ralph McKinney), (Grady H. Emerson), 344.
——Testing, resistance reduces shutdowns (J. S. Murray), *498.
Inventory (see under Records).
Iron (see Handling materials).
Iron and Steel Electrical Engineers (see Association of—).

J

Job:
——If you do your work well enough you won't have to do it (editorial comment) 239.
——Message from Bettendorf, Ia., here is a short (Practical Pete), 461.
——Responsibilities, let your men assume some (editorial comment), 436.
——You can't lift yourself by your boot straps (editorial comment), 585.

L

Ladder for industrial uses, substantial metal, *445.
Lamps (see also Lighting):
——Overvoltage on, means short life (editorial comment), 339.
——Synchronizing, voltage rating of lamps used for (Ovide C. Harris), (R. M. Bush), (Phil D. Comer), (Frederick E. Nimmcke), (C. Otto von Dannenberg), (Edward A. Gibbs), (D. W. Blakeslee), 493.
——Test, on grounded circuits (J. Elmer Housley), *395.
Lighting (see also Lamps):
——Better, in industrial plants (Roy A. Palmer), *363, editorial comment, 384.
——Circuit connections, determining lighting (Henry Mulford), *548.
——Daytime, why burn lights in the (editorial comment), 437.
——Design in illumination of factories, proper (D. W. Blakeslee), 199.
——Development in, equipment (Arthur J. Whitcomb), *107.
——Eye hazards in your plant, what and where are (editorial comment), 385.
——Glare, treating windows to prevent (A. J. Lodder), 538.
——Good, features that distinguish a (Roy A. Palmer), *476.
——Mill lights when not needed, saving in turning out (D. W. Blakeslee), 396.
——More light means more production (editorial comment), 536.
——Pattern storage building, layout of system for (D. W. Blakeslee), 594.
——Reflectors, do you need more lighting units or cleaner? (editorial comment), 585.
Lighting (Continued):
——Reflectors essential for efficient, clean (Allison J. Thompson), 154.
——Repair shop, layout of system for (J. R. Cravath), *553.
Lineshafting (see Shafting).
Linoleum, making a close seam when laying, 296.
Literature (see Books and Trade literature).
Load, making a survey of the power (H. E. Stafford), *310, editorial comment, 338.
Lubrication (see also Bearings):
——Ball bearing hanger boxes, of 351.
——Gear reductions with oil circulating systems, modernizing (Maurice C. Cockshott), *500.
——Jackshaft bearing of mill-type motor leaks oil (A. L. Gear), (E. H. Laabs), *94.
——Kink helps in automatic feeding of material (Arthur L. Greene), 394.
——Oils and greases for industrial (Frank E. Gooding), *558.
——Pressure, adapting grease cup to apply (S. H. Samuels), *351.
——Static electricity cause of shock to oilers (L. E. Beneze), 103.
Lumber, construction of a crib for piling (Donald A. Hampson), *446.

M

Magnesia to be used again, cutter for tearing up scrap (Maurice C. Cocksnott), 546.
Magnets, lifting:
——A. C., essential construction details of (Philip G. Bernholz), *105.
——Iron in cement mill, removes tramp, *297.
——Steel scrap, for handling, *250.
Maintenance (see Inspection and Maintenance).
Makeshifts are not intended for permanent use (editorial comment), 584.
Material handling (see Handling materials).
McGraw, James H. medals (editorial comment), 286.
McGraw-Hill Company buys EMF Electrical Year Book, 604.
Measurements (see Meters).
Megger for testing insulation of motors, how to use (Lee F. Dann), (Edward James), (H. Charlton), (Ralph McKinney), 344, (E. I. Pease), (William Glameyer), (C. Otto von Dannenberg), (A. C. Roe), 442.
Meters:
——Graphic, for setting overload relays, using (G. A. Sharland), *564.
——Grounds, graphic meters for detecting (R. H. Bahney), *415, editorial comment, 436.
——Overhauled, how often do you have them? (editorial comment), 286.
——Overhauling (J. D. Zook), *219.
——Power factor, connecting three-phase (Lee F. Dann), (Edward James), *388.
——Power factor, does not register (C. Otto von Dannenberg), (W. N. Goodwin, Jr.), (William P. Amanns), (B. W. Hamilton), (R. M. Bush), *593.
——Switchboard, trouble with (Edward James), *96.
——Watt-hour:
Connecting, to three-wire circuit, (Donald Ferguson), (Edwin V. Lambert), (C. Otto von Dannenberg), (Lee F. Dann), (Nathaniel W. Blanchard), *194, (Herbert King), *492.
Connecting Westinghouse type C, to 3-phase, 4-wire circuit (C. Otto von Dannenberg), (Lee F. Dann), (C. W. Roselle), *243.
Read alike, will these? (Lyle Hendricks), (J. J. Conway), (Herbert King), (C. Otto von Dannenberg), *542.
Mica, device for undercutting (Royce L. Grimes), *45.
Mills:
——Paper, power drive and motor control layout (C. S. Newcomb), *510.
——Steel:
Motors in, maintenance of large (O. Needham), *423, comment (W. J. Sternad), 547.
——Steel:
Operation, problems of (Arthur J. Whitcomb), *406.
Mistakes, let them teach their own lessons (editorial comment), 30.
Molds from plaster of paris, making patterns and (G. A. Luers), 159.
Motor bearings (see Bearings).
Motor control:
——Coal-handling equipment, interlocking the control of (Roger F. Emerson), *251.
——Compensator:
440-volt coil, emergency use of 110-volt no-voltage release on (W. L. Stevens), *350.
Handle locked to prevent starting motor, *40.
Portable unit for emergency use (J. F. Morgan), *100.
——Contactors will not close on low voltage (E. H. Laabs), 440, (J. M. Walsh), 539.
——Developments in use of (Arthur J. Whitcomb), *71.
——Paper mill power drive and, layout (C. S. Newcomb), *510.
——Relays, using a graphic meter for setting overload (G. A. Sharland), *564.
——Resistance to use, how to determine amount of plugging (Martin G. Lane), 191.
——Slip rings injure motor, will shorting (D. W. Blakeslee), (C. Otto von Dannenberg), (E. A. Finley), (Nicholas J. Weiss), (Phil. D. Comer), (John F. Byers), (Lee F. Dann), (R. M. Bush), (W. Montelius Price), 441.

*Indicates illustrated articles

390718

Motor control (Continued):
——Shunt motor having grounded field coil, emergency method of operating (L. P. Staubitz), *594.
——Starting:
D. C. motors, calculating starting resistance for (Donald Ferguson), (E. I. Pease), (P. S. Pender), (Cecil H. Green), 389.
Full voltage, of larger motors (editorial comment), 188.
How does this motor start? (R. F. Emerson), 440.
Induction, effect of full-voltage starting on, 349.
Induction motor, what happens in (editorial comment), 384.
Resistance for d.c., calculating (Edward James), (Halsey De Graw), (Edward H. Hausler), (Michael Reuter), *246.
Squirrel-cage motors across the line, throwing large (H. Banholzer), (C. Otto von Dannenberg), (F. F. Emerson), (H. D. Fisher), (L. J. Clayton), *191.
Trouble cured by applying common sense (Donald A. Hampson), *200.
Trouble, unusual combination of motor and starter (J. A. Horton), 449.
Motor drive (see also Belts, Chains, Couplings, Gears, etc.)
——Accident hazards on power transmission equipment, reducing (Harry C. Peterson), 301.
——Coupling and extra bearing saves $195 yearly, installation of flexible (N. A. Cozzens), *598.
——Developments in use of (Arthur J. Whitcomb), *71.
——Flexible, short-center, *601.
——Individual motors and silent chains (Dean W. Taylor), *214.
——Keysetting machine to power drive, changing a hand-power (W. L. Stevens), *300.
——Paper mill (C. S. Newcomb), *510.
——Pioneering with (Practical Pete), *309.
——Presses, getting more power at the die of punch, 254.
——Problem (Practical Pete), *557.
——Speed changes, securing co-operation of operators when making (Donald A. Hampson), 102.
——Speed transmission on an assembly conveyor, savings made with variable, *202.
——Special requirements, for, *200.
——Temporary, special base makes portable motor stationary for (L. C. Shearer), *450.
Motor-generator:
——Starting trouble with (Herbert King), (E. J. Morrissey), (Nicholas J. Weiss), (C. Otto von Dannenberg), 144.
——Testing small single-phase and three-phase motors, set for (C. Otto von Dannenberg), (Lee F. Dann), 144.
Motor inspection (see Inspection and Maintenance and Motor Repairs).
Motor installation and mounting:
——Ceiling as safeguard when cutting holes, shoving up, *445.
——Ceiling, on (B. Dowick), (H. F. Fox), (C. N. Shafer), (Edward James), 590.
——Columns, standardized type of platform for, *597.
——Headroom, mounting a motor with a belt guard to give (Donald A. Hampson), *451.
——Increasing size of mountings for larger motor (H. W.), *42.
——Shield protects motors from dripping moisture, removable (H. D. Fisher), *497.
Motor maintenance (see Inspection and maintenance and Motor repairs).
Motor reconnection and repair:
——Armatures:
Banding a large, under difficulties (Maurice M. Clement), 453.
Bands, eddy currents cause of trouble with (E. Kalen), *205.
Coils, cleaning strap copper (A. C. Roe), 600.
Coils, how to find the lead throw of (A. C. Roe and D. H. Braymer), *485.
Defects in, inexpensive outfit for locating (George E. Ringness), *104.
Dip and bake, how to (A. C. Roe), 400.
Dipping and baking, convenient arrangement for (A. H. Kopprasch), *302.
Dipping and baking, savings affected by, 255.
D. C., number of bars covered by brushes on wave-wound (Cecil H. Green), *292.
D. C., tested with voltmeter (C. Otto von Dannenberg), (Nathaniel W. Blanchard), 242.
Direction of winding, without changing rotation, how to change (George William Hanlon), 159.
Fan, connecting commutator leads of G. E. 25-Cycle disk (E. A. Otto), *344.
Growler for testing (P. Justus), *142.
Rewinding, for electric drill (A. C. Roe), (J. A. Clark, Jr.), (J. M. Zimmerman), 587.
Scrapped instead of repaired, when should they be (George D. Ringness), 345, (Edward James), 443.
Small, device for winding (E. H. Winkler), (L. Konstan), *590.
Speed, rewinding increased (B. Belcher), (George Ringness), (M. V. Miller), 345.
Motor reconnection and repair (Continued):
Testing equipment gave puzzling results, defective (J. A. Horton), *44.
Wave-wound, laying down commutator leads in (James H. Hanley), 303.
Winding, by machine (P. E. Chapman), *230.
Workstand for small (J. P. Kincaid), *401.
——Babbitt, precautions in the use of (Maurice C. Cockshott), 42.
——Brushes:
Chattering, cause of (Edward James), (C. N. Shafer), (William J. Mildon), (Grady H. Emerson), 589.
Spacing, obtaining proper (John E. Holtman), 257.
——Changed, should the entire motor or only a part be? (editorial comment), 189.
——Coils:
Armature, how to find the lead throw of (A. C. Roe and D. H. Braymer), *485.
Counting turns when winding, device for (George D. Ringness), 552.
Field, emergency method of operating synchronous motor having shorted (M. G. Rees), *349.
Field, locating reversed, with carbon lamps (W. L. Stevens), *596.
Purchased or made in the repair shop, should they be (J. Elmer Housley), (A. C. Roe), 147, (G. R. Hofmann), (Grady H. Emerson), (W. O. Hurlbut), (George Cropper), (G. B. Finch), (H. J. Achee), 289.
Turns in a, without opening it, how to determine (Phillip G. Bernholz), *159.
Winding, use of revolution counter in (Maurice M. Clement), *204.
——Commutators:
Bars, clamp for replacing (Donald A. Hampson), *552.
Bars, cleaning old (A. C. Roe), 600.
Black, turning (Nicholas J. Weiss), (W. C. Kalb), (Donald L. Hoare), (H. C. Mills), (Edward A. Gibbs), 35.
Interpole motor, trouble with (George Cropper), (J. M. Walsh), (Rodger F. Emerson), (G. B. H.), (Frederick Krug), (Nicholas J. Weiss), 143.
Mica, device for undercutting (Royce L. Grimes), *45.
Riveted-type, repairing (C. B. Keck), *504.
Slotting cutters, emergency method of thinning (J. A. Horton), 104.
Small, emergency alterations to (George William Hanlon), 257.
36-bar, instead of 24-bar, using (A. C. Roe), 504.
——Emergency repair insured protection against field breakdowns (Grady H. Emerson), 158.
——Failures, visual record system for (Comer D. Hazen), *517.
——Fans, removing cores of (G. H. Ennis), 302, (O. B. Eve), (A. L. Waliof), 544.
——Field cores from fractional horsepower motors, removing (Carl G. Howard), *400.
——Frame, quick repair of broken (Donald A. Hampson), 599.
——Generator, operating direct-current motor as (Nicholas J. Weiss), (W. Montelius Price), (J. M. Walsh), (C. Otto von Dannenberg), 494.
——Grounds, using an autotransformer for locating (W. B. Cone), 600.
——Humming, keeping from (Edward James), 492.
——Lighting system and equipment in repair shop, layout of (J. R. Cravath), *553.
——Oil rings were cast and turned down, how babbitt (Donald A. Hampson).
——Polyphase, single-phase operation of (R. G. Warner and W. B. Hall), *185, comment (W. L. Lodge), 298, answer (R. G. Warner), 299, comment (Charles C. Cobb, Jr.), 348.
——Pump bearings, motor trouble traced to tight (Grady H. Emerson), 156, comment (H. S. Kellogg), 499.
——Repair work study may save money (editorial comment), 339.
——Replacing motors when trouble develops (George D. Ringness), (M. V. Miller), (Edward James), (John W. Cubbage), (Grady H. Emerson), 389.
——Rotor:
Banded under difficulty, how a 750-hp. motor was (S. H. Samuels), *158.
Bars cause trouble with electric grinder, loose (B. Belcher), 255.
——Shop equipment developments, *84.
——Shops, operating and managing (George P. Svendson), *27, editorial comment, 31.
——Slow, why does this motor run? (Earle N. Dillard), (R. F. Emerson), (Frank Harle), (Edward A. Gibbs), (Edward James), (William B. Cone), 392.
——Speed change affect horsepower, how does (H. J. Achee), 33.
——Speeded up, why motor cannot be (J. J. Conway), (G. B. H.), (J. M. Walsh), (K. L. Hansen), 93.
——Two-phase motor for three-phase operation, changing (A. C. Roe), 206, (Charles R. Sugg), *289, (V. O. Misner), (Charles R. Sugg), Lee F. Dann), (S. W. Stearns), *491.
——Three-phase, broken connection cause of peculiar behaviour of (J. H. Gallant), *348.
Motor reconnection and repair (Continued):
——Variety may add spice—but (Practical Pete), *213.
——Winding:
Chorded split-loop, laying in a (A. C. Roe), *452.
Cleaning (C. N. Shafer), (William F. Garcin), (J. F. Gordon), (M. V. Miller), 542.
Coil per slot, having one (A. C. Roe), *19.
Delta-and Star-connected, advantages of (Lee F. Dann), (Charles F. Cameron), (R. B. Turner), 36.
D. C. Armatures, practical pointers and rules for (A. C. Roe and D. H. Braymer), *380, *432 connection, 502.
Field, improper connection of (J. A. Horton), *206.
Frog leg d.c. armature (W. H. Powell and G. M. Albrecht), *462.
Induction, change in (A. C. Roe), 157.
One bar per slot, that have (A. C. Roe), *136.
Re-entrancy in lap and wave (A. C. Roe and D. H. Braymer), *582.
Rewinding and repairing armatures and motors (Chester A. Williams), *524.
Rewinding data, taking and recording (A. C. Roe), *281, *333.
Speed and voltage change, for (A. C. Roe), *45.
Wave, is retrogressive or progressive, determining when a (A. C. Roe), 92.
Motor starters (see Motor control).
Motor testing (see Testing).
Motor troubles (see Motor repairs).
Motors (see also Motor control, Motor drive, Motor installation, Motor repairs):
——Developments in use of (Arthur J. Whitcomb), *71.
——Flywheels, selecting motors for machines that require (Dean W. Taylor), 43.
——Induction:
Textile mills, first one in (Practical Pete), *309.
Variations in voltage and frequency affect, how, 396.
——Nameplate data, meaning of (Edward H. Hausler), (George Ringness), 148.
——Polyphase, single-phase operation of (R. G. Warner and W. B. Hall), *185, comment (W. L. Lodge), 298, answer (R. G. Warner), 299, comment (Charles C. Cobb, Jr.), 348.
——Record system (J. F. Morgan), *297.
——Slow-speed, is it coming back? (editorial comment), 286.
——Synchronous, using a.c. generator as (Lee F. Dann), 195, (G. B. Heron), 292.
——Two-speed, advantageous applications of (Dean W. Taylor), 101.

N

New equipment for plant operation and maintenance, *601.
1924, changes in mechanical and electrical equipment, *52.
1925, construction during, new industrial (editorial comment), 90.

O

Oil:
——Circuit-breaker, inspection and testing of, 153.
——Grease and, for industrial lubrication (Frank E. Gooding), *558.
——Tanks, cleaning sludge from fuel (W. B. Clarke), 150.
——Transformer, when did you test your? (editorial comment), 238.
Old equipment, what do you do with? (editorial comment), 239.
Ovens, electric baking:
——Heat loss from, reducing (C. D. Corwin), *573.
——X-ray machine coils, speed production of (W. S. Werner), *497.

P

Packing gland, simple stuffing box without a (G. A. Luers), *301.
Painting:
——Exposed sheet-metal work (Donald A. Hampson), 394.
——Plaster and brickwork, priming coat for (Donald Maxfield), (A. J. Calhoun), 36.
——Mechanical, of industrial plants (Keene Richards), *173.
——Put broom and paint brush on your payroll (editorial comment), 536.
Partitions in office and factory, industrial (Frank E. Gooding), *23.
Path of power service:
——Electrical devices in (Arthur J. Whitcomb), *71, correction, 200.
——Mechanical equipment in (G. A. Van Brunt), *55.
Patterns and molds from plaster of paris (G. A. Luers), 159.
Pipes, standardized identification markings for, *295.
Plans are not finished until results are known (editorial comment), 188.
Plant:
——Broom and paint brush on your payroll, put (editorial comment), 536.
——Clean up outside work, now is the time to (editorial comment), 436.
——Floor sweepings, trap for, *197.
——Housekeeping in the Buick Motor Company's (Practical Pete), 405.
——Operation, one man should be responsible for (editorial comment), 537.

*Indicates illustrated articles

Plant (Continued):
——Refuse containers from oil drums, making heavy (G. A. Luers), *38.
——Troublesome problems, some (C. O. Sandstrom), 38.
——Tomorrow in mind when you plan for today, keep (editorial comment), 488.
——Wallboard for, fire-resisting (H. E. Jeddy), *235.
——Workrooms make for efficiency, healthful (editorial comment), 584.
Pneumatic handling of materials in industry (Charles L. Hubbard), *427.
Power drive (see Motor drives).
Power factor:
——Chart for, and current of three-phase motors (Charles F. Cameron), *549.
——Improved by using rotary converter as synchronous condenser (Robert W. Drake), *262.
Power service, path of (see Path of power service).
Power transmission (see Belts, Chains, Couplings Gears, Motor Drive, etc.).
Practical Pete (see Author's Index).
Pulleys:
——Bearings in loose, repairing roller (Donald A. Hampson), 597.
——Driving belts on short centers with high ratios, *43.
——Metal, quick method of lagging up a, *450.
——Record system for spare (A. J. Calhoun), *201.
——Sizes to give various speed ratios, simple chart for finding, 352.
——Trends and new practices in use of (G. A. Van Brunt), *55.
Pump as air compressor, using vacuum (R. A. Kiefer), (E. H. Laabs), 245, (C. O. Sandstrom), 343.

Q

Questions asked and answered by readers, *32, *92, *142, *190, *240, *288, *340, *386, *439, *490, *538, *586.

R

Railings, construction details of various standard, *98.
Records:
——Blueprints for easy reference, filing (S. H. Samuels), *37.
——Chart for calculating proper size of copper wire (Charles F. Cameron), *595.
——Complete data make it easier to answer questions (editorial comment), 585.
——Diaries on maintenance jobs (L. J. Clayton), 346.
——Filing rack (G. A. Luers), *197.
——Inspections of equipment, charting frequency of making, 97.
——Motor failures, visual system for (Comer D. Hazen), *517.
——Motor inspection form helps in training inspectors (C. H. Hart), *39.
——Motor, system (J. F. Morgan), *297.
——Notebook remember things you want to do, let a (editorial comment), 536.
——Rewinding data, taking and recording (A. C. Roe), *281, *333.
——Survey of the power load, making a (H. E. Stafford), *310.
——Transmission equipment, for spare pulleys and other (A. J. Calhoun), *201.
——Work-done inventory, make a (Practical Pete), *1.
Refrigeration lines, protecting hair felt insulation on (Maurice Cockshott), 446.
Relays, using graphic meter for setting overload (G. A. Sharland), *564.
Repairs (see Motor repairs).
Research data usable to practical men, making (editorial comment), 91.
Rewinding (see Motor repairs).
Rotors (see Motor repairs).

S

Safety:
——Accidents cost a billion dollars a year, industrial (editorial comment), 90.
——Best safeguard is a careful man, the (editorial comment), 584.
——Breakdowns and lost-time accidents, reducing (R. R. Thomson), *118.
——Compensator handle to prevent starting motor, locking, *40.
——Crane at point of small clearance, device for stopping (J. Elmer Housley), *99.
——Crane trolley wire when it breaks, safety device for killing live (O. E. Bricker), *101.
——Elevators past top floor, stop which prevents riding, *197.
——Engineer, and the electrical (John A. Oartel), 471.
——Eye hazards in your plant, what and where are (editorial comment), 385.
——Grounding circuits to protect maintenance men, *39.
——Illumination in industrial plants, better (Roy A. Palmer), *363.
——Inspections of equipment, charting frequency of making, 97.
——Machine guards, laying out and taking measurements, *248.
——Oilers, static electricity cause of shock to (L. E. Beneze), 103.
——Switches (see under Switches).
——Transmission equipment, reducing accident hazards on power (Harry C. Peterson), 301.
——Wheels, guard for spoked (Donald A. Hampson), *37.
Salaries hang, the peg on which good (editorial comment), 31.
Saw rigged up to cut out wooden flooring, *247.
Scrap pile, watch your (editorial comment), 91.
Shafting:
——Break, where does a lineshaft usually? (H. H. Langbehn), (E. N. Dillard), (C. Otto von Dannenberg), (H. D. Fisher), (W. A. Plant), (C. O. Sandstrom), (C. L. Hartman), 586.
——Concrete pillars, supporting on (E. I. Pease), (H. D. Fisher), (H. S. Rich), (E. L. Way), (E. H. Laabs), (C. O. Sandstrom), *240.
——Connecting lineshaft directly to motor (George D. Ringness), (Edward James), 441.
——Groundwork necessary before erecting a lineshaft (George Trimm), *519.
——Heavy-duty, on ball bearings, operating (Stanley D. Berg), 103.
——Horsepower of a shaft or clutch, how to determine (H. D. Fisher), (John J. Serrell), (E. H. Laabs), (Harry J. Smith), 540.
——Installation, planning a lineshaft (Frank E. Gooding, *418.
——Lineshaft directly to motor, connecting (Lee F. Dann), C. O. Sandstrom), (E. H. Laabs), 288.
——Machine shafts get bent in assembling, how, 500.
——Peen under inner rings of ball bearings, why, 253, comment (R. L. Brown, 300.
——Placing, and driven machine (H. S. Rich), (H. D. Fisher), (Grady H. Emerson), *34.
Signals:
——Contact device on scale beam tells when proper load is obtained, *348.
——Crane operators of overhead wires, warning (R. H. Bahney), *447.
Slate:
——Structural, industrial applications of, *532.
——Switchboard material, as a (Robert Notvest), *271.
Solder into usable form, putting odd bits of (S. H. Samuels), 205.
Soldering iron, heavy-duty, *601.
"Spanish windlass" to increase the pull, using the (S. H. Samuels), *196.
Speed (see Motor drive).
Speed reducers:
——Spur gear, construction and operation of (Warren G. Jones), 155.
——Trends and new practices in use of (G. A. Van Brunt), *55.
Springs, using cut disk as separator between two (G. A. Luers), 545.
Stairway for use around machinery (Donald A. Hampson), *196.
Starters (see Motor control).
Stators (see Motor repairs).
Steel mills (see Mills).
Storage:
——Lumber, construction of a crib for piling (Donald A. Hampson), *446.
——Pattern, building lighting system (D. W. Blakeslee), 594.
Storage batteries (see Batteries).
Stuffing box without a packing gland (G. A. Luers), *301.
Substation equipment developments, industrial (Arthur J. Whitcomb), *71.
Switchboard:
——Busbars, straightening and cleaning (S. H. Samuels), 401.
——Electric Power Club's recommendations on installation and care of power, *327.
——Installation of new (H. S. Rich), *40.
——Instruments, trouble with (Edward James), *96.
——Slate as a, material (Robert Notvest), *271.
Switches:
——Safety, requirements of (J. Elmer Housley), *123.
——Trip corrected by time-delay relay, trouble on low-voltage (J. A. Vanderpoll), *395.
Switching equipment, Electric Power Club's instructions for installing power, *378.

T

Tanks:
——Bottom rusting out, installing and preventing (C. O. Sandstrom), 563.
——Settling, reconstructing and erecting (H. R. Wass), *495.
Teamwork (see Job).
Testing:
——Armatures:
D.C., with voltmeter (C. Otto von Dannenberg), (Nathaniel W. Blanchard), *242.
Growler for, (P. Justus), *144.
——Field coil with carbon camp, locating reversed (W. L. Stevens), *596.
——Insulation:
Motor, how to use megger for (Lee F. Dann), (Edward James), (H. Charlton), (Ralph McKinney), 344, (E. I. Pease), (William Glameyer), (C. Otto von Dannenberg), (A. C. Roe), 442.
Motors, voltage for, of, 206.
Resistance reduces shutdowns (J. S. Murray, *498.
——Lamp on grounded circuits, using test (J. Elmer Housley), *395.
——Motors:
Brake for testing small and medium sizes, simple Prony (S. H. Samuels), *353.
Insulation, how to use megger for (Lee F. Dann), (Edward James), (H. Charlton), (Ralph McKinney), 344, (E. I. Pease), (William Glameyer), (C. Otto von Dannenberg), (A. C. Roe), 442.
Insulation of, voltage for, 206.
Single-phase and three-phase, motor-generator set for (C. Otto von Dannenberg), (Lee F. Dann), 143.
Testing (Continued):
Table, portable (J. F. Morgan), *297.
——Panel for, electrical equipment, layout of (J. H. Sauve), *599.
——Spare equipment also, test and maintain (editorial comment), 437.
Tools:
——Clamp for refinishing flat surfaces, low (G. A. Luers), *256.
——Corrugated iron used to keep, in order (G. A. Luers), *104.
——Drawer, attaching divided compartment to (G. A. Luers), *452.
——Drills repaired by use of brass sleeve, broken (G. A. Luers), 552.
——Fuse link, for inserting a renewable (W. L. Stevens), *198.
——Hammer for use on finished surfaces, rubber head on, 452.
——Handles, simple devices that are handy as wrench and (G. A. Luers), *157.
——Lathe, sensitive drill and tapping attachment for (G. A. Luers), *354.
——Maintenance, developments in, *84.
——Nuts or bolts, making special sockets to fit odd-size (G. A. Luers), *302.
——Power-driven, for maintenance work, portable (editorial comment), 489.
Trade literature, 47, 115, 163, 211, 259, 307, 356, 403, 459, 507, 555, 603.
Transformers:
——Connections affect rated capacity, does change in? (John E. Holtman), (A. Noeppel), (L. J. Johnson), 541.
——Delta-connected bank, grounding (Harry J. Achee), (C. Otto von Dannenberg), (L. P. Staubitz), *588.
——No-load current, draws heavy (C. Otto von Dannenberg, 492.
——Oil, when did you test your? (editorial comment), 238.
——Polarity of (S. N. Clarkson), (J. B. Hodtum), (Ernest Dickinson), (Roger F. Emerson), (Thomas M. Hunter), (Phil D. Comer), (M. F. Mitschrich), (Edwin W. Lindop), 341, (A. Boyajian), (F. Elliott Waldron), (L. C. Nichols), (Henry Mulford), (L. F. Goss), (Fred W. Paffen), (Cecil H. Green), (J. F. Peters), (Ovide C. Harris), *443.
——25-cycle on a 60-cycle circuit, operating (R. F. Emerson), (C. D. Shaffer), (C. Otto von Dannenberg), (P. Van Herk), (L. T. Johnson), (George Cropper), 33.
Transportation (see Handling materials, Trucks).
Transmission of power (see Belts, Chains, Couplings, Gears, Motor Driven etc.).
Transmission towers, how long will it take to erect these? (E. I. Pease), 388.
Turbo-generator:
——Collector rings of, trouble with (W. J. Park), (J. A. Horton), (Edward A. Gibbs), (Henry Mulford), 146.
——Windings, taking data on (A. C. Roe), *178.
Turnbuckle, preventing rods from turning with (G. A. Luers), *150.

V

Valves, abrasives for grinding small (Donald A. Hampson), 496.
Van Brunt, G. A. (Practical Pete), *262.
Vapors, fumes and gases, removing obnoxious (Charles L. Hubbard), *276.
Varnishes, insulating, composition and ageing of (H. C. P. Weber), 204.
Ventilation:
——Dust:
Removing, produced in industrial plants (Charles L. Hubbard), *320.
——Dust:
Separating, from air in industrial plants (Charles L. Hubbard), *366.
——Fumes, gases and vapors, removing obnoxious (Charles L. Hubbard), *276.
Voltage, improvised method of regulating a.c. (W. L. Stevens), *252.

W

Walls, strength of brick (C. O. Sandstrom), 439.
Washer for rags and overalls, tumbling drum (G. A. Luers), *295.
Weight of heavy machine parts, using lever to find (Donald A. Hampson), *151.
Welding:
——Arc:
Element mill, cuts repair cost in, 566.
Combination type welder, *602.
Generator and storage battery for (H. S. Rich), 100.
Two-phase set on three-phase circuit, operating (Charles R. Sugg), *146.
——Odd-time uses of, outfits in industrial plants, *495.
——Platform for mounting equipment, *100.
——Portable, trailer for making outfits, *255.
Westinghouse Electric and Manufacturing Company's plants, *2.
Winding (see Motor Repairs).
Windlass to increase the pull, using the Spanish (S. H. Samuels), *196.
Windows:
——Cleaning scaffold, portable (G. A. Luers), *97.
——Glare, treating to prevent (A. J. Lodder), 538.
Wire (see also Cables and Wiring):
——Armored, lead-sheath conductor underground, use of (Harold W. Steele), (C. Otto von Dannenberg), (Grady H. Emerson), (E. I. Pease), 544.
——Copper, chart for calculating proper size of (Charles F. Cameron), *595.
——Copper, current values required to fuse solid (Frederick Krug), 449.

*Indicates illustrated articles

Wire (Continued):
——Pyrometer leads, for (Charles L. Browne), (D. W. Blakeslee), (W. W. Lankton), (W. H. Fredrickson), (C. Otto von Dannenberg), (W. A. Bergsma), (Grady H. Emerson), (E. N. Dillard), (H. A. Nielsen), 591.
Wiring (see also Wire):
——Break in power line cause of obscure trouble (Walter C. Bischoff), 198.
——Conduit:
Cleats or bolts to concrete, attaching (S. W. Stearns), 198.
Wiring (Continued):
——Conduit:
Fittings, threadless, *601.
Trouble in power circuits run in, locating (Phil D. Comer), (Nathaniel W. Blanchard), (Grady H. Emerson), (C. Otto von Danenberg), (Donald Ferguson), H. S. Rich), (Nicholas J. Weiss), *293.
——Developments in, devices (Arthur J. Whitcomb), *109.
——Open, in mill-type building (J. H. Blair), (Lee F. Dann), (H. S. Rich), (Edwin V. Lambert), 94.
Wiring (Continued):
——Overhead electrical circuits, layout of (J. Elmer Housley), *358.
——Plug and receptacle for portable machine, protecting (H. S. Rich), *152.
——Three-phase installation, layout of typical (H. D. Fisher), (Ralph McKinney), (Lee F. Dann), *244.
——Tunnel for conduit and pipe lines (D. Fliegelman), *346.
Woodworking plant, power service layout for a (Francis A. Westbrook), *316.
Workmanship, pride in (Practical Pete), *117.

INDEX OF AUTHORS

A

ACHEE, HARRY J. Grounding delta-connected transformer bank, *588.
——How does change in speed of motor affect horsepower, 33.
——Should coils be purchased or made in the repair shop?, 290.
Albrecht, G. M. (see W. H. Powell).
Amanns, William P. Why do these meters not register, *593.
Arny, Louis W. Determining the quality of leather belts, *479.

B

BABCOCK, K. P. Organization of fire prevention in industrial works, *98.
Baber, Earl Voltage rating of fuses for 440-volt service, 95.
Bahney, R. H. Using graphic meters for detecting grounds, *415, editorial comment, 436.
——Warning crane operators of overhead wires, *447.
Banholzer, H. Throwing large squirrel-cage motors across the line, 191.
Barker, A. C. Drilling holes through plate glass, 592.
Belcher, B. Loose rotor bars cause trouble with electric grinder, 255.
——Rewinding armature increased speed, 345.
——Trouble with rewound automobile generators, 343.
Beneze, L. E. States electricity cause of shocks to oilers, 103.
Benson, Harold E. Gloves from old leather used for handling brick, 346.
——Sample and easily replaceable fuses, *600.
Bergsma, W. A. What kind of wire should be used here, 592.
Bernholz, Philip G. Construction details of a.c. magnets, *105.
——How to determine the number of turns in a coil without opening it, *159.
Berg, Stanley D. Operating heavy-duty lineshafts on ball bearings, 103.
Bischoff, Walter C. Break in power line cause of obscure trouble, 198.
Blair, J. H. Running open wiring in mill-type buildings, 94.
Blakeslee, D. W. Bearing cost decreased by using steel pipe in place of cast shell, 156.
——Drilling holes through plate glass, 592.
——Layout of lighting system for pattern storage building, 594.
——Operating motors in parallel on bridge motion of crane, 340.
——Proper design of illumination in factories, 199.
——Saving in turning out mill lights when not needed, 396.
——Voltage rating of lamps used for synchronizing, 494.
——What kind of wire should be used here, 591.
——Will shorting slip rings injure motor?, 440.
Blanchard, Nathaniel W. Connecting watt-hour meter to three-wire circuit, *195.
——Locating trouble in power circuits run in conduit, *293.
——Testing d.c. armatures with voltmeter, 242.
Boyajian, A. Polarity of transformer, 443.
Braymer, D. H. (see A. C. Roe).
Bricker, O. E. Safety device for killing live trolley wire when it breaks, *101.
Brown, R. L. Comments on why shafts peen under inner rings of ball bearings, *300.
Browne, Charles L. What kind of wire should be used here, 591.
Broyles, J. L. Voltage rating of fuses for 440-volt circuits, 95.
Burnham, George A. Selection and maintenance of oil circuit breakers, 465.
Bush, R. M. Voltage rating of lamps used for synchronizing, 493.
——Why do these meters not register, 593.
——Will shorting slip rings injure motor?, 441.
Bussmann, H. T. Voltage rating of fuses for 440-volt circuits, 95.
Butler, Ralph A. Heating of ingots by electricity, 471.
Byers, John F. Will shorting slip rings injure motor?, 441.

C

CALHOUN, A. J. Priming coat for plaster and brickwork, 36.
——Record system for spare pulleys and other transmission equipment, *201.
Cameron, Charles F. Advantages of star-and delta-connected motor windings, 36.
——Calculating proper size of copper wire, *595.
——Chart for power factor and current of three-phase motors, *549.
Carpenter, E. T. Use of 30-amp. and 60-amp. fuses, 448.
Carter, Edward D. Paralleling of alternators coupled to same shaft, 250.
Case, N. H. Trolley wire supports for monorail crane, *386.
Chapman, P. E. Winding armatures by machine, *230.
Charlton, H. How to use megger for testing insulation of motors, 345.
Chrisman, E. D. Changes in mechanical and electrical equipment, *54.
Clark, J. A., Jr. Method of rewinding armature, 587.
Clarke, W. B. Cleaning sludge from fuel oil tanks, 150.
Clarkson, S. N. Polarity of transformer, *341.
Clayton, L. J. Advantages of keeping diaries on maintenance jobs, 346.
——Comparature costs on three types of factory floors for trucking runways, 249.
——Throwing large squirrel-cage motors across the line, 193.
Clement, Maurice M. Banding a large armature under difficulties, 453.
——Novel use of revolution counter in winding coils, *204.
Cobb, Charles C., Jr. Comment on single-phase operation of polyphase motors, 348, comment (E. T. Carpenter), 448.
Cockshott, Maurice. Bearing renewals in centrifugal pump, 398.
——Cutter for tearing up scrap magnesia to be used again, 546.
——Maintenance problems in the small plant *567.
——Modernizing sets of old-type gear reductions with oil circulating system, *550.
——Protecting raw felt insulation on refrigeration lines, 446.
——Use of babbitt, 42.
Comer, Phil. D. Connecting Westinghouse type C watt-hour meter to 3-phase, 4-wire circuit, *243.
——Determining size of conductors for intermittent-rated motors, 195.
——Locating trouble in power circuits run in conduit, 293.
——Polarity of transformer, 342.
——Voltage rating of fuses for 440-volt service, 95.
——Voltage rating of lamps used for synchronizing, 493.
——Will shorting slip rings injure motor?, 441.
Cone, W. B. Making a tripod from conduit, 249.
——Rewinding 110-volt generator for 6 volts, 340.
——Using an autotransformer for locating grounds on motors, 600.
——Why does this motor run slow?, 392.
Conway, A. J. Operating motors in parallel on bridge motion of crane, 341.
Conway, J. J. Will these watt-hour meters read alike?, 542.
——Why motor cannot be speeded up, 93.
Corwin, C. D. Reducing heat loss from electric baking ovens, *573.
——What maintenance includes and how it is handled, *50.
Cozzens, N. A. Installation of flexible couplings and extra bearing saves $195 yearly, *598.
Cravath, J. R. Layout of lighting system and equipment in repair shop, *553.
Cropper, George. Commutator trouble with interpole motor, 142.
——Determining size of conductors for intermittent-rated motors, 291.
——Operating 25-cycle transformers on a 60-cycle circuit, 33.
——Should coils be purchased or made in the repair shop?, 290.
Cubbage, John W. Replacing motors when trouble develops, 389.

D

DANN, LEE F. Advantages of star-and delta-connected motor windings, 36.
——Connecting lineshaft directly to motor, 288.
——Connecting three-phase power factor meter, *388.
——Connecting watt-hour meter to three-wire circuit, *194.
——Connecting Westinghouse type C watt-hour meter to 3-phase, 4-wire circuit, *243.
——Cost of changing two-phase motors to three-phase, 492.
——How to use megger for testing insulation of motors, 344.
——Layout of typical three-phase installation, *244.
——Motor-generator set for testing small single-phase and three-phase motors, 143.
——Running open wiring in mill-type buildings, 94.
——Using a.c. generator as synchronous motor, 195.
——Will shorting slip rings injure motor?, 441.
De Graw, Halsey. Calculating starting resistance for d.c. motors, 246.
Dickinson, Ernest. Polarity of transformer, 341.
Dillard, Earle N. Trolley wire supports for monorail crane, 388.
——What kind of wire should be used here, 592.
——Where does a lineshaft usually break? 586.
——Why does this motor run slow?, 392.
Dowick, B. Mounting motor on ceiling, 589.
Drake, Robert W. Laying out short-center belt drives using idlers, *166.
——Using rotary converter as synchronous condenser, *262.

E

E., M. J. Helps on running-in bearings which heat up when new, 352.
Emerson, Grady H. Driving one generator with two engines, 243.
——Emergency repair that insured protection against field breakdowns, 158.
——Locating trouble in power circuits run in conduit, 293.
——Motor trouble traced to tight pump bearings, 156, comment (H. S. Kellogg), 499.
——Placing lineshaft and driven machine, *34.
——Replacing motors when trouble develops, 389.
——Should coils be purchased or made in the repair shop?, 290.
——Stopping breakage of gears, 490.
——Thickness of mica required for slot insulation, 344.
——Use of armored, lead-sheath conductor underground, 543.
——Voltage rating of fuses for 440-volt circuits, 245.
——What causes these brushes to chatter, 589.
——What kind of wire should be used here, 592.
Emerson, R. F. Causes of trouble in operating motors in parallel on bridge of crane, *498.
——Commutator trouble with interpole motor, 143.
——Determining size of conductors for intermittent-rated motors, 291.
——How does this motor start? 440.
——Interlocking the control of coal-handling equipment, *251.
——Operating 25-cycle transformers on a 60-cycle circuit, 33.
——Polarity of transformer, *342.
——Throwing large squirrel-cage motors across the line, *191.
——Trouble on a.c. crane corrected by dynamic braking, *448.
——Why does this motor run slow? 392.
Ennis, G. H. Removing cores of fans, 302, comment (Carl G. Howard), *400.
Eve, O. B. Removing cores from fan motors, 544.

F

F., E. B. Fuse renewals on the night shift, 41.
F., E. D. Belt slip as safety link in machine drives, *103.
Faden, J. L. Electric heat supplanted steam for preheating wood before gluing, *199.
Ferguson, Donald D. Calculating starting resistance for d.c. motors, 389.
——Connecting watt-hour meter to three-wire circuit, *194.
——Determining size of conductors for intermittent-rated motors, 291.
——Grounding secondary of 3-phase, 220-440-volt distribution system, 148.
——Locating trouble in power circuits run in conduit, 294.
Fiess, A. Trolley wire supports for monorail crane, 388.
Finch, G. B. Should coils be purchased or made in the repair shop? 290.
Finley, E. A. Will shortening slip rings injure motor? 440.
Fisher, H. D. Change in mechanical and electrical equipment, *52, editorial comment, 91.
——How to determine horsepower of a shaft or clutch, 539.
——Layout of typical three-phrase installation, *244.
——Placing line-shaft and driven machine, *34.
——Removable shield which protects motors from dripping moisture, *497.
——Supporting lineshafting on concrete pillars, *240.
——Throwing large squirrel-cage motors across the line, 193.
——Where does a lineshaft usually break? 587.
Fliegelman, David. Construction details of tunnel for conduit and pipe lines, *346.
——Ways in which sling chains are abused, 223.
Fox, H. F. Mounting motor on ceiling, 590.
Frederickson, W. H. What kind of wire should be used here? 592.

*Indicates illustrated articles

Frost, S. A. Better product with less hazard by using electric heat, *547.

G

GALLANT, J. H. Broken connection cause of peculiar behavior of three-phase motor, *348.
——Heating locomotive wheel tires for removal, *44.
Garcin, William F. Cleaning motor winding, 542.
Gear, A. L. Jackshaft bearing of mill type motor leaks oil, 94.
Gibbs, Edward A. Commutators turning black, 35.
——Grounding secondary of 3-phase, 220-440-volt distribution system, 148.
——Trouble with collector rings of turbo-generator, 146.
——Voltage rating of lamps used for synchronizing, 494.
——Why does this motor run slow? 392.
Glameyer, William. Megger for testing insulation of motors, 442.
Gooding, Frank E. Growth of well-known industrial centers, *6.
——Industrial applications of structural slate, *532.
——Industrial partitions in office and factory, *23.
——Material handling devices pay for themselves, *65.
——Planning a lineshaft installation, *418.
——Using oils and greases for industrial lubrication, *558.
Goodwin, W. N., Jr. Why do these meters not register? *593.
Gordon, J. F. Cleaning motor winding, 542.
Goss, L. F. Polarity of transformer, 444.
Green, Cecil H. Calculating starting resistance for d.c. motors, *391.
——Number of bars covered by brushes on wave-wound d.c. armatures, *292.
——Polarity of transformer, 444.
Greene, Arthur L. Dimension specification for ordering stud bolts, *353.
——Lubricating kink helps in automatic feeding of materials, 394.
Grimes, Royce L. Device for undercutting mica, *45.
Griva, John. Drilling holes through plate glass, 592.

H

H., G. B. Why motor cannot be speed up, 93.
Hall, W. B. (See R. G. Warner.)
Hamilton, B. W. Why do these meters not register? 593.
Hampson, Donald A. Abrasives to use for grinding small valves, 496.
——Checking parellelism of shafts on a chain drive, *501.
——Construction of a crib for piling lumber, *446.
——Construction of metal grating for floor openings, *546.
——Frozen motor bearing removed and repaired, *253.
——Handling long belt drive, *201.
——How babbit oil rings were cast and turned down, 354.
——How to line up a motor pinion with the gear it drives, *398.
——Mounting a motor with a belt guard to give headroom, *451.
——Painting exposed sheet-metal work, 394.
——Quick repair of broken motor frame, 599.
——Reminiscences on mechanical repairs that show the value of experience, 203.
——Repairing roller bearings in loose pulleys, 597.
——Securing co-operation of operators when making speed changes, 102.
——Simple changes in a feed-belt drive improved operation, *551.
——Simple clamp for replacing commutator bars, *552.
——Stairway for use around machinery, *196.
——Starter trouble cured by applying common sense, 200.
——Substantial but low-cost guard for spoked wheels, *37.
——Turning an ice machine shaft without removing it, 205.
——Using lever to find weight of heavy machine parts, *151.
——Yard crane overcame bad loading condition, *296.
Hanley, James H. Laying down commutator leads in wave-wound armatures, 303.
Hanlon, George William. Emergency alterations to small commutators, 257.
——How to change direction of winding armature without changing rotation, 159.
Hansen, K. L. Why motor cannot be speeded up, 93.
Harle, Frank. Why does this motor run slow? 392.
Harris, Ovide C. Polarity of transformer, 444.
——Voltage rating of lamps used for synchronizing, 493.
Hart, C. H. Motor inspection form helps in training inspectors, *39.
Hartman, C. L. Where does a lineshaft usually break? 587.
Hausler, Edward H. Calculating starting resistance for d.c. motors, 246.
——Meaning of motor nameplate data, 148.
Hazen, Comer D. Visual record system for motor failures, *517.
Hendricks, Lyle. Will these watt-hour meters read alike? 542.
Hepner, Charles R. Fuse color scheme that prevents misuse of fuses, *228, editorial comment, 238.
Heron, George B. Proper care of motor bearings essential to good service, *299.
Heron, George B. (Continued):
——Using a.c. generator as synchronous motor, 292.
Hillman, L. A. Changes that have taken place in bearings, *127.
Hoare, Donald L. Commutators turning black, 35.
Hodtum, T. B. Polarity of transformer, *341.
Hofmann, G. R. Should coils be purchased or made in the repair shop? 289.
Holtman, John E. Does change in transformer connections affect rated capacity? 541.
——Obtaining proper brush spacing, 257.
Horton, J. A. Defective armature testing equipment gave puzzling results, *44.
——Emergency method of thinning commutator slotting cutters, 104.
——Improper connection of motor field winding, *206.
——Trouble with collector rings of turbo-generator, 145.
——Unusual combination of motor and starter trouble, 449.
Housley, J. Elmer. Essentials of safety switches, *123.
——Layout of overhead electrical circuits, *358.
——Safety device for stopping crane at point of small clearance, *99.
——Should coils be purchased or made in the repair shop? 147.
——Using test lamp on grounded circuits, *395.
Howard, Carl G. Removing field cores from fractional horsepower motor, *400.
——Selecting material for small motor bearings, 599.
Howe, E. S. Brush and commutator maintenance, *575.
Hubbard, Charles L. Handling materials by air in industry, *427.
——Removing dust produced in industrial plants, *320.
——Removing obnoxious fumes, gases and vapors, *276.
——Separating dust from air in industrial plants, *366.
Hunter, Thomas M. Polarity of transformer, 342.
Huntington, R. S. Paralleling alternators coupled to same shaft, *153, comment (Edward D. Carter), 250.
Hurlbut, W. O. Should coils be purchased or made in the repair shop? 290.
Hurme, E. A. Electric heat treating applications, 469.

J

JAMES, Edward. Calculating starting resistance for d.c. motors, *246.
——Connecting lineshaft directly to motor, 441.
——Connecting three-phase power factor meter, *388.
——How can this motor be kept from humming? 492.
——How to use megger for testing insulation of motor, 344.
——Mounting motor on ceiling, 590.
——Replacing motors when trouble develops, 389.
——Thickness of mica required for slot insulation, 343.
——Trouble with rewound automobile generators, 245.
——Trouble with switchboard instruments, *96.
——Voltage rating of fuses for 440-volt circuits, 95.
——What causes these brushes to chatter? 589.
——When should an armature be scrapped instead of repaired? 443.
——Why does this motor run slow? 392.
Jeddy, H. E. Fire-resisting wallboard in industrial plants, *235.
Johnson, L. J. Does change in transformer connections affect rated capacity? 541.
Johnson, L. T. Operating 25-cycle transformers on 60-cycle circuit, 33.
——Voltage rating of fuses for 440-volt circuits, 245.
Jones, Philip C. Changes in electrical and mechanical equipment, *52.
Jones, R. F. How service conditions affect belt capacity, *265.
Jones, Warren G. Construction and operation of spur gear speed reducers, 155.
——Reducing cost when ordering bevel gears, 254.
Justus, P. Design of growler for testing armatures, *144.

K

KALB, W. C. Commutators turning black, 35.
Kalen, E. Eddy currents cause of trouble with armature bands, *205.
Keck, C. B. Repairing riveted-type commutators, *504.
Kellogg, H. S. Comment on motor trouble traced to tight pump bearings, 499.
Kiefer, R. A. Using vacuum pump as air compressor, 245.
Kincaid, J. P. Workstand for small armatures, *401.
King, Herbert. Connecting watt-hour meter to three-wire circuit, *492.
——Starting trouble with motor-generator set, 145.
——Will these wall-hour meters read alike? *542.
Konstan, L. Winding small armatures, *590.
Kopprasch, A. H. Convenient arrangement for dipping and baking armatures, *302.
Krause, F. J. H. Points to think about when repairing storage batteries, 256.
Krug, Frederick. Commutator trouble with interpole motor, 142.
——Current values required to fuse solid copper wire, 449.

*Indicates illustrated articles

L

LAABS, E. H. Connecting lineshaft directly to motor, 288.
——Contactors will not close on low voltage, 440.
——How to determine horsepower of a shaft or clutch, 539.
——Jackshaft bearing of mill type motor leaks oil, *94.
——Lining up sprockets for chain drive, 195.
——Supporting line-shafting on concrete pillars, 241.
——Using vacuum pump as air compressor, 245.
Laing, William L. Combined efficiency of elements of hoisting mechanism, 102.
Lambert, Edwin V. Accessibility of fuses is big factor in laying out power circuits, *154.
——Connecting watt-hour meter to three-wire circuit, *194.
——Running open wiring in mill-type buildings, 94.
Lane, Martin G. How to determine amount of plugging resistance to use, 191.
Langbehn, H. H. Where does a lineshaft usually break? 586.
Lankton, W. W. What kind of wire should be used here? 591.
Lindop, Edwin W. Polarity of transformer, 343.
Lodder, A. J. Treating windows to prevent glare, 538.
Lodge, W. L. Comment on single-phase operation of polyphase motors, 298, comment (Charles C. Cobb, Jr.), 348.
Luers, G. A. Attaching divided compartments to tool drawer, *452.
——Construction of foot-operated broach for cutting plate, *502.
——Corrugated iron used to keep tools in order, *104.
——Low clamp for refinishing flat surfaces, *256.
——Making heavy refuse containers from oil drums, *38.
——Making patterns and moulds from plaster of Paris, 159.
——Making special sockets to fit odd-size nuts or bolts, *302.
——Portable window cleaning scaffold, *97.
——Preventing rods from turning with turnbuckles, *150.
——Repairing broken drills by use of brass sleeve, 552.
——Rules governing fire prevention in industrial plants, 247.
——Sensitive drill and tapping attachment for lathe, *354.
——Simple and easily constructed filing rack, *197.
——Simple devices that are handy as wrench and tool handles, *157.
——Simple stuffing box without a packing gland, *301.
——Tumbling drum washer for rags and overalls, *295.
——Using cut disk as separator between two springs, *545.

M

MAXWELL, Donald. Priming coat for plaster and brickwork, 36.
Maxwell, Howard. Do ball and roller bearings justify their cost? *12.
McEwan, Lachlan A. Trolley wire supports for monorail crane, *387.
McKelway, G. H. Determining size of conductors for intermittent-rated motors, 195.
——Making a sleeve splice on heavy cables, 596.
——Practical pointers on charging storage batteries, 549.
——Voltage rating of fuses for 440-volt circuits, 245.
McKinney, Ralph. How to use megger for testing insulation of motors, 345.
——Layout of typical three-phase installation, *244.
——Thickness of mica required for slot insulation, 344.
Mildon, William J. What causes brushes to chatter? 589.
——Will flexible couplings reduce gear shock on motors? 538.
Miller, M. V. Cleaning motor winding, 542.
——Replacing motors when trouble develops, 389.
——Rewinding armature increased speed, 345.
Mills, H. C. Commutators turning black, 35.
Misner, U. O. Cost of changing two-phase motors to three-phase, 491.
Mitschrich, M. F. Polarity of transformer, *342.
Morgan, J. F. Portable compensator unit for emergency use, *100.
——Portable motor testing table and motor record system, *297.
Morrissey, E. J. Starting trouble with motor-generator set, 144.
Mulford, Henry. Determining lighting circuit connections, *548.
——Polarity of transformer, 443.
——Trouble with collector rings of turbo-generator, 145.
Murray, J. S. Testing insulation resistance reduces shutdowns, *497.
——Use of an improved type of sleeve bearing, *473.

N

NEEDHAM, O. Maintenance of large motors in steel mills, *423, comment (W. J. Sternad), 547.
Neustedter, W. J. Trouble caused by plugging elevator motor, 96.
Newcomb, C. S. Paper mill power drive and motor control layout, *510.
Nichols, L. C. Polarity of transformer, 443.

Nielsen, H. A. What kind of wire should be used here? 592.
Nimmcke, Frederick. Voltage rating of lamps used for synchronizing, 493.
Noeppel, A. Does change in transformer connections affect rated capacity? 541.
Norris, P. E. Space heaters in battery manufacture, *251.
Notvest, Robert. Slate as switchboard material, *271.

O

OARTEL, John A. Safety and the electrical engineer, 471.
Oppmann, A. W. Designating fuse capacities by different colors, 40.
Otto, E. A. Connecting commutator leads of G.E. 25-cycle desk fan armatures, *344.

P

PAFFEN, Fred W. Polarity of transformer, *444.
Palmer, Roy A. Better illumination in industrial plants, *363, editorial comment, 384.
——Features that distinguish a good lighting system, *476.
Park, W. J. Trouble with collector rings of turbo-generator, 145.
Paulsen, W. E. Details of construction and some possible uses of a growler, *502.
Pease, E. I. Calculating starting resistance for d.c. motors, *390.
——How long will it take to erect these towers? 388.
——Megger for testing insulation of motors, 442.
——Supporting lineshafting on concrete pillars, 240.
——Use of armored, lead-sheath conductor underground, 544.
Pender, P. S. Calculating starting resistance for d.c. motors, *391.
——Lining up conduit on ceiling beams, 93.
——Lining up sprockets for chain drives, *32.
——Voltage rating of fuses for 440-volt service, 95.
Pilkington, H. E. Putting an acid fume discharge system outside the building, *545.
Pete (see Practical Pete).
Peters, J. F. Polarity of transformer, 444.
Peterson, Harry C. Reducing accident hazards on power transmission equipment, 301.
Plant, W. A. Where does a lineshaft usually break? 587.
Powell, W. H., and G. M. Albrecht. Troy leg d.c. armature windings, *462.
Practical Pete. Are you a bloodhound or a setter? *557.
——Generator installed 43 years ago, *509.
——Generators still running after 30 years of service, *165.
——Here is a short message from Bettendorf, Ia., *461.
——Housekeeping in a factory, *405.
——Just a word on the side about my new boss, *262.
——Make a work-done inventory covering 1924, p*1.
——Maybe you haven't noticed it, but—, 218.
——Pioneering with motor drives, *309.
——Pride in workmanship, *117.
——Reminiscences of a trouble shooter for a machinery builder, *131, *182.
——Thanks! Many thanks! *49.
——Variety may add spice—but, *213.
——When you dance someone pays the fiddler—, *357.
Price, W. Montelius. Operating direct-current motor as generator, 494.
——Will shorting slip rings injure motor? 441.
Price, W. T. Changes in mechanical and electrical equipment, 113.

R

READ, E. K. (see M. J. Wohlgemuth).
Rees, M. G. Emergency method of operating synchronous motor having shorted field coil, *349.
Reuter, Michael. Calculating starting resistance for d.c. motors, *246.
Rhoads, J. Edgar. Reclaiming leather belting, 190.
Rich, H. S. Generator and storage battery for arc welding, 100.
——Grounding secondary of 3-phase, 220-440-volt distribution system, 148.
——Handling installation of new switchboard, *40.
——Locating trouble in power circuits run in conduit, 294.
——Motor-driven crushing device, *155.
——Placing lineshaft and driven machine, *34.
——Protecting plug and receptacle for portable machine, *152.
——Running open wiring in mill-type buildings, 94.
——Supporting lineshafting on concrete pillars, 240.
——Trouble caused by plugging elevator motor, 96.
Richards, Keene. Changes in mechanical and electrical equipment, 113.
——Mechanical painting of industrial plants, *173.
Ringness, George D. Connecting lineshaft directly to motor, 441.
——Device for counting turns when winding coils, *552.
——Locating defects in armature, *104.
——Meaning of motor nameplate data, 148.
——Replacing motors when trouble develops, 389.
——Rewinding armature increased speed, 345.
Ringness, George D. (Continued):
——Trouble with rewound automobile generators, 245.
——When should an armature be scrapped instead of repaired? 345.
Roe, A. C. Changing two-phase motor for three-phase operation, 206.
——Cleaning old commutator bars and strap copper armature coils, 600.
——Determining when a wave winding is retrogressive or progressive, 92.
——How to dip and bake armatures, 400.
——Laying in a chorded split-loop winding, *452.
——Megger for testing insulation of motors, 442.
——Method of rewinding armature, 587.
——Methods for taking data on turbo-generator windings, *178.
——Rewinding motor for speed and voltage change, *45.
——Should coils be purchased or made in the repair shop? 147.
——Taking and recording rewinding data, *281, *333.
——Thickness of mica required for slot insulation, 344.
——Using a 36-bar commutator in place of one having 24 bars, 504.
——Windings having one coil per slot, *19.
——Windings that have one bar per slot, *136.
——Working out a change in winding of an induction motor, 157.
Roe, A. C., and D. H. Braymer. How to find the lead throw of armature coils, *485.
——Practical pointers and winding rules for d.c. armatures, *380, correction, 502, *433.
——What re-entrancy means in lap and wave windings, *582.
Roselle, C. W. Connecting Westinghouse type C watt-hour meter to 3-phase, 4-wire circuit, *243.

S

SAMUELS, S. H. Adapting grease cup to apply pressure lubrication, *351.
——"Cat's paw" hitch for lifting heavy loads, *393.
——Devise for bending copper busbars, *547.
——Filing blueprints for easy reference, *37.
——How a 750-hp. motor was banded under difficulty, *158.
——Making a sleeve splice on heavy cables, *152.
——Putting odd bits of solder into usable form, 205.
——Simple Prony brake for testing small and medium sizes of motors, *353.
——Straightening and cleaning busbars, 401.
——Using the "Spanish windlass" to increase the pull, *196.
Sandstrom, C. O. Connecting lineshaft directly to motor, 288.
——Installing tanks to prevent bottom rusting out, 563.
——Some troublesome problems in an industrial works, 38.
——Stopping breakage of gears, 491.
——Strength of brick walls, 439.
——Supporting lineshafting on concrete pillars, 241.
——Using vacuum pump as air compressor, 343.
——Where does a lineshaft usually break? 587.
Sauve, J. H. Layout of panel for testing electrical equipment, *599.
Schaeffer, George H. Report of A. I. & S. E. E. electric heat committee, 469.
Seede, J. A. Electric melting furnaces, 470.
Serrell, John J. How to determine horsepower of a shaft or clutch, 539.
Shafer, C. N. Cleaning motor winding, 541.
——Mounting motor on ceiling, 590.
——What causes these brushes to chatter, 589.
Shaffer, C. D. Operating 25-cycle transformers on a 60-cycle circuit, 33.
Sharland, G. A. Using a graphic meter for setting overload relays, *564.
Shearer, L. C. Special base makes portable motor stationary for temporary drives, *450.
Smith, Harry J. How to determine horsepower of a shaft or clutch, 540.
Stafford, H. E. Making a survey of the power load, *310, editorial comment, 338.
Staubitz, L. P. Emergency method of operating shunt motor having grounded field coil, *594.
——Grounding delta-connected transformer bank, *588.
Stearns, S. W. Attaching conduit, cleats or bolts to concrete, 198.
——Cost of changing two-phase motors to three-phase, 492.
——Two ways to get longer life from eaves troughs, 150.
Steele, Harold W. Use of armored, lead-sheath conductor underground, 543.
Sternad, W. J. Comment on maintenance of large motors in steel mills, 547.
Stevens, W. L. Changing a hand-power key-setting machine to power drive, *300.
——Emergency use of 110-volt no-voltage release on 440-volt coil compensator, *350.
——Improvised method of regulating a.c. voltage, *252.
——Locating reversed field coil with carbon lamp, *596.
——Tool for inserting a renewable fuse link, 198.
Sugg, Charles R. Cost of changing two-phase motors to three-phase, *491.
——Reconnecting two-phase motor for three-phase operation, *289.
——Trouble in operating two-phase arc welder set on three-phase circuit, *146.
Svendson, George P. Operating and managing motor repair shops, *27, editorial comment, 31.

T

TAYLOR, Dean W. Advantageous applications of two-speed motors, 101.
——Failure of test lamps to show open fuse, 99.
——Individual motors and silent chains, *214.
——Selecting motors for machines that require flywheels, 43.
Thompson, Allison J. Clean reflectors essential for efficient lighting, 154.
Thomson, R. B. Reducing breakdowns and lost-time accidents, *118.
Trimm, George. Groundwork necessary before erecting a lineshaft, *519.
Turner, R. B. Advantages of star- and delta-connected motor windings, 36.

V

VAN BRUNT, G. A. Mechanical equipment in the path of power service, *55.
——Recent changes made in National Electrical Code, 529, editorial comment, 537.
Vanderpoll, J. A. Trouble on low-voltage trip corrected by time-delay relay, *395.
Van Herk, P. Operating 25-cycle transformers on a 60-cycle circuit, 33.
Von Dannenberg, C. Otto. Connecting watt-hour meter to three-wire circuit, *194.
——Connecting Westinghouse type C watt-hour meter to 3-phase, 4-wire circuit, *243.
——Emergency excitation for generators, 386.
——Grounding delta-connected transformer bank, *588.
——Grounding secondary of 3-phase, 220-440-volt distribution system, 148.
——Locating trouble in power circuits run in conduit, 293.
——Megger for testing insulation of motors, 442.
——Motor generator set for testing small single-phase and three-phase motors, 143.
——Operating d.c. motor as generator, 494.
——Operating 25-cycle transformers on a 60-cycle circuit, 33.
——Starting trouble with motor-generator set, 145.
——Testing d.c. armatures with voltmeter, *242.
——Throwing large squirrel-cage motors across the line, 191.
——Transformer draws heavy no-load current, 492.
——Use of armored, lead-sheath conductor underground, 543.
——Voltage rating of lamps used for synchronizing, 493.
——What kind of wire should be used here, 592.
——Where does a lineshaft usually break? 586.
——Why do these meters not register? 593.
——Will shorting slip rings injure motor? 440.
——Will these watt-hour meters read alike? 542.

W

W. H. Increasing size of mounting for larger motor, *42.
Waldron, F. Elliott. Polarity of transformer, 443.
Wallof, A. L. Removing cores from fan motors, 544.
Walsh, J. M. Commutator trouble with interpole motor, 142.
——Contactors will not close on low voltage, 539.
——Operating d.c. motor as generator, 494.
——Why motor cannot be speeded up, 93.
Warner, R. G., and W. B. Hall. What happens during single-phase operation of polyphase motors, *185, comment (W. L. Lodge), 298, answer (R. G. Warner), 299.
Wass, H. R. Reconstructing and erecting settling tanks, *495.
Way, E. L. Supporting lineshafting on concrete pillars, 241.
Weber, H. C. P. Composition and ageing of insulating varnishes, 204.
Weiss, Nicholas J. Commutator trouble with interpole motor, 143.
——Coommutators turning black, 35.
——Locating trouble in power circuits run in conduit, 294.
——Operating d.c. motor as generator, 494.
——Starting trouble with motor-generator set, 144.
——Will shorting slip rings injure motor? 440.
Werner, W. S. Electric baking speeds production of X-ray machine coils, *497.
Westbrook, Francis A. Power service layout for a woodworking plant, *316.
Wheeler, Paul. Enclosing and lubricating silent chain drives, *133.
Whitcomb, Arthur J. Electrical devices in the path of power service, *71, correction, 200.
——Problems of steel mill operation, *406.
Williams, Chester A. Rewinding and repairing armatures and motors, *524.
Wineman, W. H. Air hoist saves floor space in steel chip disposal, *347.
Winkler, E. H. Winding small armatures, *590.
Wohlgemuth, M. J., and E. K. Read. Selection and maintenance of oil circuit breakers, 468.
Wynd, L. A. Changes in mechanical and electrical equipment, 113.

Z

ZIMMERMAN, J. M. Method of rewinding armature, 588.
Zook, J. D. Overhauling electrical measuring instruments, *219.

*Indicates illustrated articles